

Department of Geography Tinsukia College

৫ নং বাঘজান তৈলক্ষেত্রৰ দুর্যোগ— এক ভৌগোলিক অধ্যয়ন



ডিব্ৰুগড় বিশ্ববিদ্যালয়ৰ স্নাতক কলা শাখাৰ ষষ্ঠ বাৰ্ষিকৰ ভূগোল বিষয়ৰ
পাঠ্যক্রমৰ অংশিক অংশৰ পৰি পূৰক অংশ হিচাপে প্ৰস্তুত কৰা প্ৰকল্প

*Examined.
Shehu
8/07/22*


জ্যোতি ধাদুমীয়া
ৰোল নং- 19110044
পঞ্জীয়ন নং- S1932039
ভোগোল বিভাগ
তিনিচুকীয়া মহাবিদ্যালয়
তিনিচুকীয়া, অসম

DEPARTMENT OF GEOGRAPHY
TINSUKIA COLLEGE, TINSUKIA

Certificate

I hereby certify that under my supervision, Jyoti Dhadumia of the
Department of Geography, Class B.A 6th Semester Roll No. 19110044
Registration No. S1932039 Tinsukia College, Tinsukia, has conducted the fieldwork
and presented this report entitled କମର ବାସନ୍ତୀର ବିଭିନ୍ନ ଅଂଶ
ସାଧାରଣ - ଏକ ଭୌଗୋଳିକ ଅଧ୍ୟୟନ

He / she has complied with all the standards outlined in the Department's rules and regulations as well as the chosen protocols for completing the field research. Under my direction, fieldwork is conducted using primary data gathering techniques and information gathered from a variety of reliable sources.



(Ms. Neha Boruah)

Faculty,

Department of Geography

Tinsukia College



ଶ୍ରୀ 4/2/22 Hearl
Geography Department
Tinsukia College
(Dr. K. Kalita)
HoD & Associate Professor
Department of Geography
Tinsukia College, Tinsukia


Principal
TINSUKIA COLLEGE
TINSUKIA